

Bases for $\phi 12$ 、 $\phi 18$

SB-H





Material:
PA 66 black

SB-V



Material:
PA 66 black


BASES FOR $\phi 12$ 、 $\phi 18$



Sensor tester — S-TER

For fast field checks of various sensor types
(inductive, capacitive, photoelectric and ultrasonic)10...30V.

- Suitable for PNP and NPN devices, N.O. And N.C. Versions
- Automatic PNP/NPN recognition
- LED and acoustic indicators
- Build-in steel target (non-standardized) for checking inductive sensors.
- Power supply from a single 9V battery(type IEC 6LR61).
- LED battery-state indication.
- Charger and rechargeable battery available (ATE-0000-022).
- Build-in step-up voltage converter.
- Automatic switch off after approx.30 sec. of non-use.



Note:

Coming Soon : Part numbers with underline
In Preparation: Part numbers with a line through the middle